



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	6606	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	2=Trace		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	20				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 559

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0559.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 327

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

**Image Status:** Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	6608	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	100				
<b>Comments:</b>	MH 01521239						

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 561

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0561.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

← Cross Country Blvd →

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 327

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	6608	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	4=Major		
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 560

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0560.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No:

327

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	6612	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	200				
<b>Comments:</b>	MH 01521237						

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 562

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0562.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 327

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

**Image Status:** Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	7	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	6614	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate		
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	80				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 563

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0563.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No:

327

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	8	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6614		Cross Country	Blvd		
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	80		
<b>Comments:</b>					

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 564

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0564.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 327

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

**Image Status:** Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	327	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR07
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	9	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6704		Cross Country	Blvd		
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	25		
<b>Comments:</b>					

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 565

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0565.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 32  
Setup No. 2  
327

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: <u>10/18/04</u>	Start Time: <u>1050</u>
Crew: <u>T2</u>	Street Location: <u>Cross Country Blvd</u>		
US MH: <u>1520924</u>	DS MH: <u>1521194</u>	Number of Segments: <u>7</u>	Test Length: <u>1488'</u>
Plugged US: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Plugged DS: <u>Y</u> <input checked="" type="radio"/> <u>N</u>	# of Blowers <u>1(2)3</u>	Ground: <u>Dry</u> Moderate Wet
Plugs Removed? <u>Y</u> <input checked="" type="radio"/> <u>N</u>	Recorder: <u>Bob Blank</u>	Comments: <u>—</u>	

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004Leader Form

Sketch No: 327

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\327.tif

**Image Status:** Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6312		Cross Country	Blvd

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	25		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 567

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0567.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY


Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 3  
328

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 8	Test Length: 1281'
US MH: 1521194	DS MH: 1521212	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blunt	Comments: =
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N			
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			



**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 328

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	10	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	6402	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	200				
<b>Comments:</b>	MH 01522219						

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 574

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0574.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 3  
328

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 8	Test Length: 1281'
US MH: 1521194	DS MH: 1521212	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: Y N	Plugged DS: Y N	Plugs Removed: Y N	Recorder: Bob Blunt
Comments: =			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	11	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	6402	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	100				
<b>Comments:</b>	MH 01522035						

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 575

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0575.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 3

# BUREAU OF WATER AND WASTEWATER SMOKE TEST INSPECTION FORM

328 ✓

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd		
US MH: 1521194	DS MH: 1521212	Number of Segments: 8	Test Length: 1281'
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugs Removed? (Y) M	Recorder: Bob Brown	Comments: —	
<b>FIELD SKETCH</b> (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

<b>CREW COMMENTS</b>
----------------------

Last Revised 9/16/2004

Leader Form

Sketch No: 328

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	12	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6406		Cross Country	Blvd

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 3

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

328 ✓

TEST LOCATION				
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430	
Crew: T2	Street Location: Cross Country Blvd			
US MH: 1521194	DS MH: 1521212	Number of Segments: 8	Test Length: 1281'	
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: (Dry)	Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Blunt	Comments: —		
<b>FIELD SKETCH</b> (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)				

Sketch No: 328

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6312		Cross Country	Blvd		
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	60		
<b>Comments:</b>					

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 568

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0568.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 3  
328

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 8	Test Length: 1281'
US MH: 1521194	DS MH: 1521212	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blunt	Comments: =
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 328

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	6312	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	4=Major		
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 569

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0569.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM

Page 1 of 2  
Smoke Set No. 22  
Setup No. 3

328

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd		
US MH: 1521194	DS MH: 1521212	Number of Segments: 8	Test Length: 1281'
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Brown	Comments: —	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Sketch No: 328

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6314		Cross Country	Blvd

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 3  
328

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 8	Test Length: 1281'
US MH: 1521194	DS MH: 1521212	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blunt	Comments: =
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N			
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 328

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6314		Cross Country	Blvd

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	30		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 570

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0570.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM

Page 1 of 2  
Smoke Set No. 22  
Setup No. 3

328

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd		
US MH: 1521194	DS MH: 1521212	Number of Segments: 8	Test Length: 1281'
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Brown	Comments: —	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Sketch No: 328

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	6314	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	2=Trace		
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	30				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 571

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0571.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 3

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

328

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd		
US MH: 1521194	DS MH: 1521212	Number of Segments: 8	Test Length: 1281'
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Brown	Comments: —	
<b>FIELD SKETCH</b> (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Sketch No: 328

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	7	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	6316	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	50				
<b>Comments:</b>	MH 01522215						

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 572

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0572.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 3  
328

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 8	Test Length: 1281'
US MH: 1521194	DS MH: 1521212	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blunt	Comments: =
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 328

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	8	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6400		Cross Country	Blvd		
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>	4=Major
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	50		
<b>Comments:</b>	MH 01522217				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 573

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0573.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 22  
Setup No. 3

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

328

TEST LOCATION				
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430	
Crew: T2	Street Location: Cross Country Blvd			
US MH: 1521194	DS MH: 1521212	Number of Segments: 8	Test Length: 1281'	
Plugged US: (Y) N	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: (Dry)	Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Blunt	Comments: —		
<b>FIELD SKETCH</b> (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)				

Sketch No: 328

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	328	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	9	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6400		Cross Country	Blvd

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 3  
328

**BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1430
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 8	Test Length: 1281'
US MH: 1521194	DS MH: 1521212	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blunt	Comments: =
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

**CREW COMMENTS**

Last Revised 9/16/2004  
Leader Form

Sketch No: 328

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\328.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	329	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	01_WR06
<b>Observer ID:</b>	B	<b>Crew:</b>	T-2	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	6302	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	13= Storm Main	<b>Location:</b>	14=Other	<b>Severity:</b>	4=Major		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0				
<b>Comments:</b>	unknown drainage						

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 576

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1018-2004\T-2\PLAYER\_B\B\_2004\_1018Image0576.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


## FIELD SKETCH

Page 1 of 2  
Smoke Set No. 28  
Setup No. 4  
329 (23)

 **BUREAU OF WATER AND WASTEWATER  
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/18/04	Start Time: 1615
Crew: T2	Street Location: Cross Country Blvd.	Number of Segments: 6	Test Length: 530'
US MH: 1521212	DS MH: 1521142	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Plugs Removed? (Y) N	Recorder: Bob Bont
Comments:			

**FIELD SKETCH** (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



**CREW COMMENTS**

Last Revised 9/16/2004 Leader Form

Sketch No: 329

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\329.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.